

---

## TECHNICAL SERVICE BULLETIN

**TO:** All Uniden Private Radio Communications Dealers,  
Distributors and Warranty Service Stations


**REFERENCE:** IMH4100DT / IMU3100KT Mobile Radios

**SUBJECT:** Receiver Front-End RF Overloading  
**(Replaces TSB NO. 233)**

---

**GENERAL:** Prevents Receiver Muting.

1. Cut Trace
2. Add 1k ohm resistor



SCHEMATIC DIAGRAM

