

---

## TECHNICAL SERVICE BULLETIN

**TO:** All Uniden Commercial Communication Dealers,  
Distributors and Warranty Service Stations

**REFERENCE:** MRS804ZX Repeaters

**SUBJECT:** ARX800B Logic Board software version Mis-shippment

---

**GENERAL:** During the months between (and including) October 1995 and January 1996, Uniden had shipped MRS804ZX repeaters containing the old version 4.6 rather than the current version 4.92.

If you have purchased them during those months, you may have obtained the wrong version software. The version software can be verified by looking at U15 and U16 chips on the logic board inside the repeater.

If you do have the old version software, you can contact the Technical Support facility and ask for an advanced replacement of those chips only if the repeater with the version 4.6 was purchased during the two dates mentioned above. The new version will be sent out to you after Uniden have verified the facsimile copy of your invoice. Once you have received the new version, the old version chips must be sent back to us in the same mailing package within 30 days to avoid being charged for the new version chips.

If you have purchased a repeater containing version 4.6 before October 1995 and wish to have the repeaters upgraded, you can call customer service to order an upgrade kit version 4.92 (Uniden part# ARX876A49).

**NOTE:** All the repeaters grouped together should not have mixed versions for various reasons such as interconnect incompatibility. If there are any questions concerning the software, please contact Technical Support Representative at the 800 number listed above.