



TSB NO.244
DATE: 01 / 12 / 2001

Uniden® PRC
Private Radio Communications

TECHNICAL SERVICE BULLETIN

TO: All RELM / Uniden PRC Communication Dealers,
Distributors and Warranty Service Stations

REFERENCE: SMU250KTST

SUBJECT: DTMF and Function Tones

GENERAL: It has been brought to our attention that on the last shipment of SMU250KTST a running change was made to the DTMF and Function tone circuitry.

DESCRIPTION OF CHANGE: The capacitance values of C606 and C607 were changed from 68pf to 100pf.

PUROSE OF CHANGE: To improve cold temperature operation of the DTMF and Function tones. In colder climates these tones would not operate properly until the radio warmed up.

RADIOS AFFECTED: Radios in serial number range 0400001 through 04000189 are the only units that require the capacitors to be change. The running change took effect at serial number 04000190.

WARRANT INFORMATION: Follow the standard warranty procedures for parts and labor reimbursement.

RELM COMMUNICATIONS

7100 Technology Drive, West Melbourne, Florida 32904
800-648-0947 – Email service@RELM.com