
TECHNICAL SERVICE BULLETIN

TO: All Uniden Private Radio Communication Dealers,
Distributors and Warranty Service Stations

REFERENCE: AMX105A

SUBJECT: Microphone Hang-up Button

GENERAL: It has been brought to our attention that on our last shipment of microphones, it is possible for the screw to come loose that secures the back plate and hang-up button. Some may require to be re-tightened and should only take about 3 minutes.

WARRANTY INFORMATION: There will be no warranty labor reimbursement provided.